ADDING STEP OF PHOSPHORUS

ADDING STEP OF PHOSPHORUS

GETTERING STEP

CRYSTALLINE SILICON FILM 305

Fig. 3C


HEAT TREATMENT STEP IN REDUCING ATMOSPHERE

ACTIVE LAYER 306

LACTIVE LAYER 306

LACTIVE LAYER 307

Fig. 3D



GETTERING STEP

